RIFIFZY

Picklist Print

November-24-11 9:13:35 AM

Work Order ID:

76932

Parent Item:

D3234-1

Parent Item Name:

Doubler

Start Date: 11/24/11

Required Date: 11/24/11

Start Qty: 8.00

Required Qty: 8.00

Comments:

IPP Rev:A New Issue 08-08-14 JLM Verified By:EC IPP Rev:B 08-12-18 as per ECN08-582 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3234-1		Manufactured	No				Each	4.0000		8		-	
Doubler													

Location Loc Qty Loc Code ST179

November-24-11 8:46:12 AM

Item ID Item Name	Warehouse ID Location ID	Lot Number	Last Trans Date	Lot by She	If Life Dt Lot Code	Type Code	Comments
D3234-1 Doubler	Main Warehouse ST179	76676	11/22/11	4.0000	QC21		
	Main Warehouse ST233	70900	11/21/11	2.0000	QC21		
	Main Warehouse ST233	71140	11/21/11	6.0000	QC21		
	Main Warehouse ST233	76577	11/21/11	~0000 X	W		
			Total:	17.0000	-		

Work Order ID 70900 Friday, June 17, 2011 7:35:27 AM											Page 1		
Revision ID:	D3234-1 Doubler			Accept					Setup	Start Stop			
200111 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	6/16/2011	Start Qty: 2.00 Req'd Qty: 2.00			Cust Item I Customer:	D:					E IORINION O	 	
Approvals:	Process Plan:QC:		Date: _//- ()(/-)	//Tooling: SPC (Y/N):	Date:			Run Start Stop					
Sequence ID/ Work Center ID)	Operation Description		Set Up/ Run Hours	Tool ID		Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp	
Draw Nbr	Rev	ision Nbr											
D3234	Rev	, В											
Waterjet FLOW CNC Waterjet			per Dwg D3234 □Dwg Rc necessary	0.00 0.00 v: <u>R</u> □Prog Rev:_ <u>∫</u>	- □2-			BI	1- <u>6-</u>	33 Z	(3)	:	
QC Quality Control	. ž	QC2- Inspect parts of	machine FAI/FAIB	0.00				@	NI-6:	-33.			
120 QC Quality Control		QC8- Inspect parts - s	econd check	0.00 E Wo	6/73			(P)					

• ,

1 62

Work Order ID 71140 Thursday, June 23, 2011 12:32:40 PM											Page 1		
Item ID: D3234-1 Revision ID: Item Name: Doubler				Accept					Setup Sta	1 18811187			
Start Date: Required Date: Reference:	6/23/2011 7/5/2011	Start Qty: 6.00 Req'd Qty: 6.00			Cust Item l Customer:	ID:				110011101	DIRCO FAR ILEA		
Approvals:		nn: MF	Date: -06-23 Date:	_	Date:			Ė	Run Stai Sto		1516 151 1151 1551 1516 151 151 1551		
Sequence ID/ Work Center ID)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp		
Draw Nbr	Rev	ision Nbr		.,									
D3234	Rev	В											
Waterjet FLOW CNC Waterje	t	FLOW WATER JET Memo 1-Cut as po Deburr if n	er Dwg D3234 - 13Dwg Rev:_ ecessary	0.00 0.00 S [JProg Rev:	<u>P</u> 172-			BI	-6-57		3		
QC Quality Control		QC2- Inspect parts off r	nachine FAI/FAIB	0.00				(B.1	-G-27		·		
120 QC Quality Control		QC8- Inspect parts - sec	cond check	0.00 S W	lo6 by		-	Élo	2)				